

Xesar 2.2 Release Notes

Important information:

You can download the new Xesar software version from the respective EVVA homepage:
<https://www.evva.com/int-en/products/electroniclockingsystemsaccesscontrolsystems/xesar/xesarsoftwaredownload/>

Xesar Software V2.2.38.43 (published on July 8th, 2020)

Tablet APP: 2.2.38.46

Firmware version:

Xesar handle:	0.428
Xesar escutcheon:	0.502 new
Xesar cylinder:	0.324
Xesar wall reader:	0.324
Xesar wall reader control unit:	0.324
Xesar online wall reader control unit:	0.324

IMPORTANT:

To guarantee the faultless functionality of your system, an unconditional implementation of the update is necessary. Necessary maintenance tasks must be carried out after the update!

SW & FW corrections and improvements

The following improvements have been made:

- Improved battery life for escutcheon
- Correction of the RFID reading function for escutcheon

Tasks to be performed:

- Software update (download and execute installer file V2.2.38.43)
- Firmware update for Xesar escutcheons
- Carry out maintenance tasks
- Manual update of the Xesar Tablet APP due to certificate renewal

IMPORTANT:

After the software update, the tablet app is **NOT** automatically updated when it is synchronized for the first time. The existing APP must first be deleted manually on the tablet and then the new APP must be reinstalled.

To manually update the tablet app, please follow the instructions in the Xesar System Manual 1.1 for version 2.2 | 05/2018 | Chapter 26.6 Manual installation / removal of the Xesar app

https://www.evva.com/fileadmin/user_upload/Dokumente/Handb%C3%BCher/Xesar/2.2/Xesar_Systemhandbuch_V2.2_EN.pdf

Xesar Software V2.2.38.30 (published on 22.06.2018)

1 Software bug elimination and improvements

- Bugfixes have also been implemented:
- Firmware version 0.414: Independently identifies any potentially applicable motor block on the escutcheon and starts an attempt to resolve the issue.
- Fault when synchronising with Xesar tablet eliminated.

2 Codingstation

- The discontinuation of the HID OMNIKEY 5421 coding station has made a hotfix for Xesar 2.2 necessary to be able to use the HID OMNIKEY 5422 successor product.

Xesar Software V2.2.38.28 (published on 27.09.2017)

3 Software bug elimination and improvements

The following bugs have been eliminated:

- Authorisation profiles not taken over in the event of a high number of persons on the person list
- Error when processing authorisation profiles if the time profile is deleted when using the central time profile
- Error after having deleted a door that is used as part of an authorisation profile
- Areas that have been assigned to a person using a user's authorisation profile are not shown in user authorisations.
- Doors added to the list of doors at risk following firmware update
- The maintenance task counter on the dashboard did not increased after having directly deleted a person from the user list

Xesar Software V2.2.38.26 (published on 27.03.2017)

1 Virtual network

- Connecting up to 123 Xesar updater wall readers

2 Tablet

- In Xesar 2.2 the use of more than one tablet to manage a system is possible.
- Automatic door detection
- The tablet "Chiligrreen E-Board MX753" will be discontinued with the release of Xesar 2.2. This tablet cannot be used with Xesar 2.2. In Xesar systems with version less than 2.2, the tablet can be used.

3 Technical improvements

- Improvements in the battery life of Xesar components

- Improvements around LPCD (Low Power Card Detection)
- Masterkey access, although if blacklist corrupt in component
- Troubleshoot database errors

4 Other New Features

- Multiple time profiles per person
 - Several Xesar facilities per Xesar installation
 - Android 5.0.x support
 - Importing Xesar facilities
 - The Xesar 2.2 software is installed on the system computer in addition to an existing Xesar software version. An existing system can then be imported by import function in Xesar 2.2. The database import is only supported by versions 1.1, 2.0 and 2.1.
 - In Xesar 2.2 the database backup is done every hour. Moreover, should a database backup may be necessary, this is possible with the backup button on the bottom left of the dashboard.
 - Manual Database Backup
 - Creating maintenance groups (several tablets)
 - Create automatic closure strips
 - Assistance through the "Getting Started"- and "Quick Start Guide"- Manual
 - Windows 10 compatibility
 - Various GUI improvements
-

Xesar Software V2.1.37.17 (published on 09/12/2015)

1 Virtual network

- **Connecting up to 14 Xesar updater wall readers**
- Up to 14 Xesar wall readers can be connected to the system via LAN as updaters using the updater control unit
- Updater with or without door function
- Installation must be operated in 24/7 mode
- Updater functions:
 - Extending the media validity period
 - Upgrading media
 - Transferring blacklists
 - Synchronising events
 - Transferring the battery status

2 Dashboard

- Overview of the current system status at a glance thanks to the dashboard. Obtain an overview of the system's security on one page. Access the corresponding detailed views from here.

3 System update: 1.1 -> 2.1, 2.0 -> 2.1

- Direct system update from 1.1 or 2.0 to 2.1

4 Firmware update: 1.1 (including hotfix) -> 2.1, 2.0 -> 2.1

- Direct firmware update from 1.1 or 2.0 to 2.1

5 Showing doors with old components on the dashboard

- List of outstanding door component updates on the dashboard

6 Schedule-based backups

- The automatic backup is run every hour

7 Managing major systems with enhanced performance

- Managing systems with several hundred media units and doors in one system

8 Translations in 10 languages

- English, German, French, Dutch, Italian, Czech, Polish, Slovakian, Spanish, Portuguese

9 Door component resets

- Door components can be set to construction mode on site, for instance after having removed them by mistake. As a result, it is possible to locally reset components in the event of errors.

Attention! Important notice:

EVVA tablet system updates and installing third-party apps:

We explicitly point out that the EVVA tablet must be used to synchronise system components and the Xesar operating software **ONLY**.

Tablet operating system updates or an installation of third-party apps is not permitted and may cause errors within the Xesar system.

For security reasons we recommend to always keep the system up-to-date in terms of the software version. This guarantees the highest possible level of security and functionality within the system.

As a result, you will also benefit from the most recent functions and potential bugfixes.

The following changes result from the market launch of Xesar 2.1 on 09/12/2015:

- We will discontinue support for Xesar 1.0 installations.
Consequently, we will no longer provide software changes, extensions or hotfixes for software version 1.0.

In the event of system issues or if you would like to implement extensions within the Xesar system (V1.0), we recommend to update to system version 1.1 free of charge. Version 1.1 can then be updated to the most recent Xesar version 2.1 at any time. Click here to download: [Download X2.1](#)

Xesar software V2.0.36.17 (published on 24 June 2015)

Virtual network

- Transfer access events using identification media
- Transfer blacklist entries using identification media
- Transfer "Unlocking attempt by medium" notifications using identification media
- Transfer "Identification medium deleted by door component" notifications using identification media
- Display the status of blocked identification media in the software
- Transfer the battery status using identification media

Additional new functions

- New dashboard with door and identification media states
 - Display opening attempts by "Lost/blocked" identification media
 - Display valid identification media which have been blocked in the software
 - Display doors with an out-of-date blacklist
 - Display doors with low battery
 - Display media with an out-of-date media status (memory extension for use with virtual network)
 - Display out-of-date identification media
 - Display key credits
 - Display the Software^{plus} package
- New notifications when handling identification media
- Automatic identification media upgrade from 1.1 to 2.0
- Software^{plus} package to enable the virtual network
- Firmware update from 1.1 to 2.0 possible in in construction mode
- Log featuring software users' activities
- Several time slots (up to 12) per days possible for persons
- Several time slots possible per day (up to 3) for office mode profiles
- Universal templates for personal, time-based profiles
- Universal template for office mode profiles
- List of maintenance tasks
- Enhanced access protocols (for persons)
- Improved KeyCredit input
- Variable periods of media validity
- Display the remaining media validity in the person list including a warning icon X days prior to expiry
- Additional information available in the person list (time-based profile, MasterKey, replacement medium)
- New software languages
 - Spanish
 - Portuguese

Improvements

- Office mode does not start if there is a "Battery low" warning
- Various GUI improvements
- Help menu with links to
 - Manuals
 - Website

- Coding station drivers
 - Support form for problems with KeyCredits
 - Various bug fixes
-

Xesar Software V1.1.33.11 (07-08-2014)

- Scope of functions like V1.1.33.9
 - System requirements adjustment for Windows
 - Windows 7 – 32-Bit
 - Windows 8.1 – 32-Bit
-

Xesar software V1.1.33.9 (24-06-2014)

1 General

- New languages: Italian, Slovakian, Czech, Polish
- Indicates the serial number of the door component
- Various GUI improvements
- Various software bug fixes
- Firmware update files for various bug fixes

2 Security

- Automatically generated super user password for increased security
- Admin password set up during installation process
- Emergency opening key replaced by "MasterKey" function
- Assignment of master key authorisations (at maximum 15 per system, e.g. fire service key)

3 Data availability

- Automatic database backup
- Information regarding the consequences of uninstalling the software

4 Improved usability

- Simpler start-up by importing persons from csv files
- Shows doors' area assignments
- Shows authorised persons per door and area

- Door administration directly in the door area
- Access event filter
- Information regarding password selection
- Shows the software version number in the header
- Shows the app version on the tablet